










3

Order	(L*W) MM
①	830*283=1
②	830*283=1
③	810*280=1
④	270*78=2
⑤	270*283=2
⑥	269*261=1
⑦	270*262=1
⑧	270*70=1
⑨	270*60=1
⑩	467*300=1
⑪	313*300=1




A




ø15*13mm
=35

B




ø8*40mm
=35

C




ø8*40mm
=8

F



ø20*0.3mm=35

G




25*65*25mm
=4

I



4*14mm
=26

J



ø20*8mm
=2

K




ø10*43mm
=2

L





ø6*70mm
=2

N-N




ø20*10mm
=4

1




2




B=2* 

3




A=2* 

4




B=1* 

5




A=1* 

6




B=4* 

7




A=4* 

8




B=28* 
 C=8* 
 N-N=4* 


9


 $A=14 \times \text{[Screw Symbol]}$


10




11


 $A=14 \times \text{[Screw Symbol]}$

12



 $I=2 \times \text{[Screw Symbol]}$

13




14

In same level




G=2* 
I=12* 



15





In same level

G=2* 
I=12* 



16





17




18



19




20



K=2*


21

L=2*
J=2*




22

J=2*



23

OK!



24